

NATIONAL ARCHIVES
PACIFIC SOUTHWEST REGION

~~RESTRICTED~~
~~SECURITY INFORMATION~~
Pacific Southwest Region

R

REPOSITORY

COLLECTION

RG 326 ATOMIC ENERGY COMMISSION

~~RESTRICTED~~

~~SECURITY INFORMATION~~
Pacific Proving Ground

DECLASSIFIED PER DOE
LETTER DATED JULY, 15, 1994
FROM ANTON SINISGALLI TO
STANLEY S. NIXON

BOX No.

193207 (#60) A16305 326-6680133

FOLDER

CONTRACT AT (29-2)-20 1953
MEDICINE, HEALTH, & SAFETY 3-3 CONTAMINATION
& DECONTAMINATION

HAN - 1271

19 February 1953

Holmes and Narver, Inc.,
APO 187, c/o Postmaster
San Francisco, California

~~THIS MATERIAL CONTAINS INFORMATION AFFECTING
THE NATIONAL DEFENSE OF THE UNITED STATES
WITHIN THE MEANING OF THE ESPIONAGE LAWS,
TITLE 18, U.S.C. SECS. 793 AND 794, THE TRANSMISSION
OR REVELATION OF WHICH IN ANY MANNER TO
AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW.~~

SUBJECT: DECONTAMINATION PROGRAM - SITE URSULA

BEST COPY AVAILABLE

Gentlemen:

Mr. Jones informs me that the decontamination program, Site Ursula, previously suggested by Mr. Ghelias, has been well done and that cooperation has been good on the part of Holmes & Narver supervision and workmen, but that it is lagging.

Now that the campsite at Ursula has had its radiation reduced to a low radiation level, it is important that the level of the surrounding highly contaminated vegetated areas be reduced. Otherwise, we may find the camp being recontaminated due to material being blown or washed back. It is recommended that the above objective be achieved in the following manner:

1. Blade 3 to 6" of south side of island wherever it has not been previously scraped moving in a westerly direction. Extreme caution should be exercised in the removal of the hot, scraped material to prevent recontamination.
2. Repeat the above procedure on that area lying west and north of the camp area. Be sure in scraping that all windows and other surface material are removed.
3. Remove all contaminated trash and piles of contaminated dirt from the camp area.
4. After the completion of the above, all remaining vegetated areas should be scraped.

The goal is to reduce the entire island to a general background of between 2 and 4 mr/hr. A rad-safe representative will be on hand each day to assist in the achievement of this work. In order that methods may be properly evaluated, it is important that the above instructions be followed to the word with no improvising and additions other than might be suggested by the rad-safe representative on location. The exact procedure used can thus be recorded and evaluated accordingly.

DECLASSIFIED PER DOE
LETTER DATED JULY 15, 1994
FROM ANTON SINISGALLI TO
STANLEY S. NIXON

~~RESTRICTED~~
~~SECURITY INFORMATION~~

3839

MEDICINE, HEALTH & SAFETY

~~RESTRICTED~~ Pacific Southwest Region

DECLASSIFIED PER DOE
LETTER DATED JULY 15, 1994
FROM ANTON SINISGALLI TO
DIANE S. NIXON

Radioisotope Program - Site 1574 (Continued):

All contaminated materials should be disposed of directly into the currents at either end of the island where it must be carried into the lagoon away from any island.

As we previously agreed, this program has first priority at the island location and must be rapidly accomplished so that we may be able to present the results to Mr. Spain upon his arrival.

Very truly yours,

H. H. LEWIS
AEC Resident Engineer

HHL:etj

cc: WFO, Albuquerque
H & H, Los Alamos
L. G. Chalins
Chromal
Central

DECLASSIFIED PER DOE
LETTER DATED JULY 19, 1994
FROM ANTON SINISGALLI TO
DIANE S. NIXON

~~RESTRICTED~~

